

INSPECTION REPORT REVIEW  
POTENTIAL HAZARDOUS WASTE SITE

5 FD 24-1-5  
(269)

SITE NAME : General Motors Corp.  
LOCATION : Arlington  
SITE NUMBER: TXD 23 00018004  
SURVEY DATE: 6/27/89 INSPECTED BY: STATE (FIT) TAT OTHER: \_\_\_\_\_  
LABORATORY : CLP EPA OTHER

RECEIVED FROM: Ed Stevra DATE RECEIVED: 8/4/89

SAMPLE TYPE(s): None One Sludge measurement was referenced.

SOIL off / on -site SURFACE WATER off / on -site GROUND WATER off / on -site DRINKING WATER off / on -site

CONTAMINANT(s): (Organics) (Inorganics) Radionuclides Microbiological

FOLLOW UP (Y/N):

☒ (Re)Sampling Requested ☒ Locate Drinking Water Sources  
☒ Further Action is URGENT ☒ Keep Site Active ("N"=No Further Action)  
☒ Concur with Report Recommendations

SUMMARY: This assessment involves an active automobile Assembly & painting plant which has operated for over 40 years. All hazardous waste are collected, separated, drummed & hauled off for disposal. The remaining wastewater is discharged to the Arlington municipal sewer. This is no ground water usage in the area and no surface water releases. All drinking water at plant and in nearby area is supplied by municipal facilities. There were two spills noted at the site & both were handled appropriately.

In view of the information contained in this report, I do not ~~believe~~ believe the site presents and present or future danger to drinking water, and would not recommend any further action at this site.

158470



F. Waven Novis 8/5/89  
ENGINEER/REVIEWER

Concurrence:

William Bush 9/05/89